SAFETY DEFECT/NONCOMPLIANCE NOTICES RECEIVED DURING MAY 2021

Published September 16, 2021

CHILD SEATS:

None during May 2021.

EQUIPMENT:

B&W Custom Truck Beds, Inc. (B&W) is recalling certain 5/8" Stainless Steel Locking Receiver Hitch Pins, part number TS51237 and TS51237JD. A defective hitch pin lock can be removed without a key, allowing the ball mount to detach from the receiver tube. A detached ball mount can allow the towed trailer to separate, increasing the risk of a crash. Dealers and will replace the locking hitch pin, free of charge. Owner notification letters were mailed May 17, 2021. Owners may contact B&W customer service at 1-620-473-3664.

21E-042

Thule, Inc. (Thule) is recalling certain Thule Tepui Hybox Tepui Wedge part number 901110, Thule Tepui Hybox part number 901100, Tepui Hybox wedge part number 8001HB203, and Tepui Hybox part number 8001HB103 and 8001HB112 rooftop tents. The rooftop tent shell may crack at the point where the mounting rails attach and detach from the vehicle. A detached rooftop tent may become a road hazard, increasing the risk of a crash. Thule will provide a refund or replacement rooftop tent, free of charge. Owner notification letters were mailed May 13, 2021. Owners may contact Thule customer service at 1-855-216-7375.

21E-045

Freedman Seating Company (Freedman) is recalling certain GO-ES Double Flipseat, part number 46183, and GO-ES Double Rigid Seat, part number 92585 passenger seats. The seat belt retractor may lock when the vehicle is on an incline. As such, these seats fail to comply with the requirements of Federal Motor Vehicle Safety Standards numbers 208, "Occupant Crash Protection" and 209, "Seat Belt Assemblies." A passenger may remove their seat belt when the retractor locks, increasing the risk of injury. Freedman will provide inspection and repair instructions, free of charge. Notification letters were mailed on June 15, 2021. Owners may contact Freedman customer service at 800-443-4540.

21E-046

Lippert is recalling certain Hehr 6400 Series Windows built between 10/01/2018 and 08/13/2020. The adhesive that bonds the vented portion of the window may fail. Adhesive failure may cause the vent portion of the window to detach, increasing the risk of a crash or injury. Dealers will inspect the windows, and replace the vent if necessary, free of charge. Notification letters were mailed July 2, 2021. Owners may contact Lippert customer service at 1-574-538-4514.

21E-047

TIRES:

None during May 2021.

SAFETY DEFECT/NONCOMPLIANCE NOTICES RECEIVED DURING MAY 2021

Published September 16, 2021

VEHICLES:

Arcimoto Inc (Arcimoto) is recalling certain 2019-2021 FUV, 2020 Deliverator, 2020-2021 Roadster, and 2021 Rapid Responder motorcycles. The Steering Angle Sensor (SAS) may have been incorrectly calibrated, causing the SAS to fail to or incorrectly detect a fault. The inverters may apply unequal torque after a failure mode is detected, causing over steer and increasing the risk of a crash. A service technician will update the firmware and replace the idler arm, free of charge. Arcimoto does not intend to send any dealer or distributor notifications, as it has neither dealers nor distributors at this time. Owner notification letters were mailed May 27, 2021. Owners may contact Arcimoto customer service at 1-541-683-6293.

21V-307

Hyundai Motor America (Hyundai) is recalling certain 2021 Santa Fe vehicles equipped with 2.5-litre Turbo engines. The fuel pipe connecting the high pressure fuel pump to the fuel rail may not have been tightened properly. An insufficiently tightened fuel pipe may leak fuel, increasing the risk of a fire. Dealers inspected and tightened the fuel pipe connection, free of charge. The affected vehicles have been repaired and therefore no owner notification letters will be sent. Owners may contact Hyundai customer service at 1-855-371-9460. Hyundai's number for this recall is 206.

21V-308

Chrysler (FCA US, LLC) is recalling certain 2019-2021 Alfa Romeo Stelvio and 2020-2021 Alfa Romeo Giulia vehicles. Hard braking may cause the Anti-Lock Brake System (ABS) Hydraulic Control Unit (HCU) rotor shaft to separate, a reduction of braking assist, and a loss of ABS. The loss of braking assistance and ABS functionality can reduce overall braking performance, increasing the risk of a crash. Dealers will replace the ABS HCU, free of charge. Owner notification letters are expected to be mailed August 12, 2021. FCA US notified certain customers on 06/29/2021 that a remedy is available. Owner notification letters were mailed on June 29, 2021. Owners may contact FCA US LLC customer service at 1-800-853-1403.

21V-309

Chrysler (FCA US LLC) is recalling certain 2021 Jeep Cherokee vehicles. The transmission oil cooler hose may have been incorrectly cured, allowing transmission fluid to leak. A transmission fluid leak increases the risk of a fire. Dealers will inspect and replace the hose, free of charge. Owners notification letters were mailed May 18, 2021. Owners may contact Chrysler customer service at 1-800-853-1403. Chrysler's number for this recall is Y18.

21V-310

Arcimoto Inc (Arcimoto) is recalling certain 2019-2021 FUV, 2021 Rapid Responder, 2020 Deliverator, 2020-2021 Roadster. Due to a software error, communication between inverters may time out, possibly resulting in an unexpected battery shutdown. A battery shutdown causes an immediate loss of power, increasing the risk of a crash. A service technician to reprogram the inverter firmware, free of charge. Owner notification letters were mailed May 27, 2021. Owners may contact Arcimoto customer service at 1-541-683-6293.
Note: Vehicles previously repaired under Recall 19V834 will need to return for the new remedy.

21V-311

SAFETY DEFECT/NONCOMPLIANCE NOTICES RECEIVED DURING MAY 2021

Published September 16, 2021

Blue Bird Body Company (Blue Bird) is recalling certain 2018-2022 All American buses. The sealing washer may not seat correctly in the pilot bore holes, allowing the high pressure fuel rail assembly to leak. A fuel leak in the presence of an ignition source increases the risk of a fire. The remedy for this recall is still under development. Owner notification letters were mailed on July 30, 2021. Owners may contact Blue Bird customer service at 1-478-822-2242. Blue Bird's number for this recall is R21BH-SB.

21V-312

Blue Bird Body Company (Blue Bird) is recalling certain 2018-2022 All American vehicles. The sealing washer may not seat correctly in the pilot bore holes, allowing the high pressure fuel rail assembly to leak. A fuel leak in the presence of an ignition source increases the risk of a fire. The remedy for this recall is still under development. Owner notification letters were mailed on July 30, 2021. Owners may contact Blue Bird customer service at 1-478-822-2242. Blue Bird's number for this recall is R21BH-NSB.

21V-313

Arcimoto Inc (Arcimoto) is recalling certain 2019-2021 FUV, 2020 Deliverator, 2021 Rapid Responder motorcycles. The seat belt retractor spool sleeve may be cracked, allowing broken pieces to block the seat belt from retracting. A seat belt that fails to retract increases the risk of injury. A service technician will replace the seat belt retractor, free of charge. Interim owner notification letters were mailed on June 22, 2021. Owner notification letters were expected to be mailed July 1, 2021. Owners may contact Arcimoto customer service at 1-541-683-6293.

21V-314

Ducati North America (Ducati) is recalling certain 2017-2020 Monster 797, Monster 1200, Supersport, 2016-2020 XDiavel, and 2018-2020 Monster 821 motorcycles. Air may permeate the rear bake system. Air in the system may reduce effectiveness of the rear brakes, increasing the distance required to stop and the risk of a crash. Dealers will install new rear brake hoses, free of charge. Owner notification letters were mailed on June 28, 2021. Owners may contact Ducati customer service at 1-888-391-5446.

21V-315

Ford Motor Company (Ford) is recalling certain 2016-2019 Explorer vehicles. The retention pins could loosen and allow the roof rail covers to detach from the vehicle. A detached roof rail cover can create a road hazard, increasing the risk of a crash. Dealers will install push-pins and replace any damaged rail clips and roof rail covers, as necessary, free of charge. Interim owner notification letters were mailed on June 22, 2021. Owners may contact Ford customer service at 1-866-436-7332. Ford's number for this recall is 21S22.

21V-316

Jayco, Inc. (Jayco) is recalling certain 2021 Travel Trailer Jay Feather Micro trailers. The spare tire carrier could break at the bend radius or gusset. A broken spare tire carrier could detach, becoming a road hazard and increasing the risk of a crash. Dealers will install two Z-brackets, free of charge. Owner notification letters were mailed on June 9, 2021. Owners may contact Jayco customer service at 1-800-283-8267. Jayco's number for this recall is 9901566.

21V-317

SAFETY DEFECT/NONCOMPLIANCE NOTICES RECEIVED DURING MAY 2021

Published September 16, 2021

Porsche Cars North America, Inc. (Porsche) is recalling certain 2021 Cayenne GTS, Cayenne GTS Coupe, 2020-2021 Cayenne Coupe, Cayenne S Coupe, Cayenne E-Hybrid Coupe vehicles. The passenger seat back heating element was not installed and may impact the calibration of the Occupant Classification System. The front passenger air bag may fail to deploy, increasing the risk of injury. Dealers will install a heating element, free of charge. Owner notification letters were mailed June 25, 2021. Owners may contact Porsche customer service at 1-800-767-7243. Porsche's number for this recall is AMB0.

21V-318

Shyft Group is recalling certain 2017-2022 Spartan RV Chassis K2 and K3 vehicles. The sealing washer may not seat correctly in the pilot bore holes, allowing the high pressure fuel rail assembly to leak. A fuel leak in the presence of an ignition source increases the risk of a fire. The remedy for this recall is still under development. Interim owner notification letters were mailed on June 23, 2021. Owners may contact Shyft Group customer service at 1-800-543-4277. Shyft Group's number for this recall is 21-11.

21V-319

Triple E Recreational Vehicles (Triple E) is recalling certain 2020-2021 Unity U24FX, U24Rl, U24MB, U24CB, U24TB, U24IB, 2020-2021 Wonder W24MB, W24FTB, W24RTB, and 2020 Serenity S24CB recreational vehicles. The auto generator start remote harness wires may be damaged by the generator fan. Damaged wires may cause an electrical shock, increasing the risk of injury. Dealers will bundle the wires with nylon ties, free of charge. Owner notification letters were mailed May 19, 2021. Owners may contact Trible E customer service at 1-877-992-9906. Trible E's number for this recall is CA#9927-1.

21V-320

Volkswagen Group of America, Inc. (Volkswagen) is recalling certain 2017 Touareg GP, Tiguan, Golf A6, E-Golf GP, CCF, 2016-2017 Passat GP, 2018-2019 Golf R GP, and 2018 Atlas vehicles. These internal-use vehicles were sold without confirmation that they were built to all applicable regulatory requirements and may have been modified prior to sale. As such, these vehicles may fail to comply with the requirements of various Federal Motor Vehicle Safety Standards. Vehicles that do not meet all regulatory requirements may have an increased risk of injury, crash, or fire. Volkswagen will repurchase the vehicles. Owner notification letters were mailed May 20, 2021. Owners may contact Volkswagen customer service at 1-800-893-5298. Volkswagen's number for this recall is 01F1.

21V-321

Oshkosh Corporation (Oshkosh) is recalling certain 2021 S-Series vehicles. The auxiliary axles may not have been properly secured and may detach. A detached axle may cause a loss of vehicle control, increasing the risk of a crash. A technician will inspect and, as necessary, replace any improperly installed fasteners, free of charge. Owner notification letters were mailed on May 26, 2021. Owners may contact Oshkosh customer services at 1-888-686-7278.

21V-322

Spartan Fire, LLC is recalling certain 2017-2020 Gladiator and MetroStar vehicles. The sealing washer may not seat correctly in the pilot bore holes, allowing the high pressure fuel rail assembly to leak. A fuel leak in the

presence of an ignition source increases the risk of a fire. The remedy for this recall is still under development. The manufacturer has not yet provided a schedule for recall notification. Owners may contact Spartan Fire customer service at 1-517-543-6400.

21V-323

Ford Motor Company (Ford) is recalling certain 2019 Transit T150, T250, T350 vehicles equipped with aluminum alloy wheels. The wheel mounting surface of the axle flange may be warped and cause the wheel studs to fracture. Fractured studs may allow the wheel to detach, increasing the risk of crash. Dealers will inspect and if necessary, replace the rear axle shaft assembly, axle shaft mounting bolts, and rear wheel lug nuts, free of charge. Owner notification letters were mailed on June 28, 2021. Owners may contact Ford customer service at 1-866-436-7332. Ford's number for this recall is 21S21.

21V-324

Airstream, Inc. (Airstream) is recalling certain 2020-2021 Globetrotter travel trailers. The adhesive on the overhead cabinet doors may fail. The doors may separate and fall on vehicle occupants, increasing the risk of injury. Dealers will inspect and replace the cabinet doors as necessary, free of charge. Owner notification letters were mailed July 6, 2021. Owners may contact Airstream customer service at 1-877-596-6505 or 1-937-596-6111 ext. 7401 or 7411.

21V-325

Daimler Trucks North America, LLC (DTNA) is recalling certain 2018-2021 Freightliner Custom Chass XC Chassis, 108SD, Custom Chass XB Chassis, Business Class M2, 114SD, and Western Star 4700 vehicles. The sealing washer may not seat correctly in the pilot bore holes, allowing the high pressure fuel rail assembly to leak. A fuel leak in the presence of an ignition source increases the risk of a fire. Dealers will replace the fuel rail and fuel lines, free of charge. Interim owner notification letters were mailed on June 21, 2021. Owners may contact DTNA customer service at 1-800-547-0712. DTNA's number for this recall is FL-886.

21V-326

Daimler Trucks North America, LLC (DNTA) is recalling certain 2018-2021 Thomas Built Buses Saf-T-Liner HDX School Bus. The sealing washer may not seat correctly in the pilot bore holes, allowing the high pressure fuel rail assembly to leak. A fuel leak in the presence of an ignition source increases the risk of a fire. The remedy for this recall is still under development. Interim owner notification letters were mailed on June 21, 2021. Owners may contact DTNA customer service at 1-800-547-0712. DTNA's number for this recall is FL-886.

21V-327

PACCAR Incorporated (PACCAR) is recalling certain 2021 Peterbilt 348 and 579 vehicles. The spring brake chamber may have been assembled with incorrect springs that were out of specification, which may cause the pressure plate to shift. The pressure plate may tear the diaphragm, causing a loss of air pressure and increasing the risk of a crash. Dealers will replace brake chambers, free of charge. Owner notification letters were mailed on July 9, 2021. Owners may contact PACCAR (Peterbilt) customer service at 1-940-591-4220. PACCAR's number for this recall is 21PBE.

21V-328

Spartan Fire, LLC is recalling certain 2009-2021 Gladiator and MetroStar emergency vehicles. The fire water pump solenoid may corrode internally, causing a loss of power to the pump control module. A loss of power to the pump control module can cause a loss of water pressure for fighting fires, increasing the risk of injury. Dealers will replace suspect solenoids, free of charge. Owner notification letters were mailed on July 9, 2021. Owners may contact Spartan Fire customer service at 1-517-543-6400.

21V-329

Eldorado National-California, Inc. (Eldorado National-California) is recalling certain 2017-2020 Axess, EXRM, and XHF vehicles. The sealing washer may not seat correctly in the pilot bore holes, allowing the high pressure fuel rail assembly to leak. A fuel leak in the presence of an ignition source increases the risk of a fire. Dealers will inspect and replace the rail as necessary, free of charge. Owner notification letters were mailed on June 18, 2021. Owners may contact Eldorado National-California customer service at 1-951-684-6868.

21V-330

Kia Motors America (Kia) is recalling certain 2013-2015 Optima and 2014-2015 Sorento vehicles previously recalled under recall 20V-519. Brake fluid may leak inside the Hydraulic Electronic Control Unit (HECU), possibly resulting in an electrical short. An electrical short in the HECU increases the risk of a fire while parked or driving. Owners are advised to park outside and away from other vehicles and structures until the recall repair is completed. Dealers will install a new multi-fuse, and inspect the HECU for leaks, replacing the HECU if necessary, free of charge. Owner notification letters were mailed on July 2, 2021. This recall supersedes previous NHTSA recall number 20V-519. Owners may contact Kia customer service at 1-800-333-4542. Kia's number for this recall is SC212.

21V-331

E-One Incorporated (E-One) is recalling certain 2017-2021 Cyclone 2, Cyclone N, Quest 2, Typhoon, and Typhoon N vehicles. The sealing washer may not seat correctly in the pilot bore holes, allowing the high pressure fuel rail assembly to leak. A fuel leak in the presence of an ignition source increases the risk of a fire. Dealers will inspect and replace the rail as necessary, free of charge. Owner notification letters were mailed out on May 28, 2021. Owners may contact E-One customer service at 1-352-237-1122.

21V-332

Kovatch Mobile Equipment Corp. (KME) is recalling certain 2012-2021 KME Custom Chassis. The sealing washer may not seat correctly in the pilot bore holes, allowing the high pressure fuel rail assembly to leak. A fuel leak in the presence of an ignition source increases the risk of a fire. Dealers will inspect the rail threads, and replace the rail as necessary, free of charge. Owner notification letters were mailed on July 2, 2021. Owners may contact KME customer service at 1-800-235-3928.

21V-333

Rosenbauer America (Rosenbauer) is recalling certain 2016-2021 Commander, Warrior, Avenger, and 2019 Commercial M2 106 vehicles. The sealing washer may not seat correctly in the pilot bore holes, allowing the high pressure fuel rail assembly to leak. A fuel leak in the presence of an ignition source increases the risk of a fire. Dealers will inspect and replace the rail as necessary, free of charge. Interim owner notification letters were

mailed on July 9, 2021. Owners may contact Rosenbauer customer service at 1-651-462-1000.

21V-334

Ducati North America (Ducati) is recalling certain 2015-2021 Monster 821, 2014-2021 Monster 1200 S/STD, and 2016-2019 Monster 1200 R motorcycles. The rear brake hoses may be susceptible to heat damage. Damaged brake hoses may cause the rear brakes to fail, increasing the risk of a crash. Dealers will replace the rear brake hoses, free of charge. Owner notification letters were mailed on July 12, 2021. Owners may contact Ducati customer service at 1-888-391-5446.

21V-335

Lamborghini (Automobili Lamborghini) is recalling certain 2021 Urus vehicles. Cracks may develop on the surface of the engine cylinder bore. Cracks may cause engine damage and a stall or an oil leak, increasing the risk of a crash or fire. Dealers will replace the engine, free of charge. Owner notification letters were mailed on June 25, 2021. Owners may contact Lamborghini at 1-866-681-6276. Lamborghini's number for this recall is L636-R.03.21.

21V-336

Altec Industries, Inc. (Altec) is recalling certain 2014-2021 TDA-58 aerial devices. The chains used to tie down the TDA-58 for transport may break. A broken tie-down chain may allow the TDA-58 to shift during transport, increasing the risk of a crash. Altetc will install new tie-down points, D-rings, and provide revised loading instructions, free of charge. Owner notification letters were mailed on July 7, 2021. Owners may contact Altec customer service at 1-877-462-5832. Altec's number for this recall is CSN 821.

21V-337

Equipment Technology, L.L.C. (ETI) is recalling certain 2019-2020 ETI ETC37IH vehicles. The tilt cylinders on the utility bucket may fail, allowing unintentional bucket movement. Unintentional bucket movement can increase the risk of injury and/or death. ETI will replace the tilt cylinders, free of charge. Owner notification letters were mailed on June 17, 2021. Owners may contact ETI customer service at 1-405-748-3841.

21V-338

Volkswagen Group of America, Inc. (Audi) is recalling certain 2021 Audi SQ7, RSQ8, RS7, RS6 AVANT, and SQ8 vehicles. Cracks may develop on the surface of the engine cylinder bore. Cracks may cause engine damage and a stall or an oil leak, increasing the risk of a crash or fire. Dealers will replace the engine, free of charge. Owner notification letters were mailed July 9, 2021. Owners may contact Audi customer service at 1-800-253-2834. Audi's number for this recall is 10G9.

21V-339

Equipment Technology, L.L.C. (ETI) is recalling certain 2018-2021 ETC37IH and ETC40IH vehicles. The weld between the outrigger assembly and the body's sub-frame assembly may be inadequate, which could result in failure of the aerial unit during use. Failure of the aerial unit can increase the risk of injury. ETI will inspect the welds, and repair or replace the rear shear plates, free of charge. Owner notification letters were mailed on June 22, 2021. Owners may contact ETI customer service at 1-405-748-3841.

SAFETY DEFECT/NONCOMPLIANCE NOTICES
RECEIVED DURING MAY 2021

Published September 16, 2021

21V-340

Porsche Cars North America, Inc. (Porsche) is recalling certain 2021 Cayenne Turbo, Cayenne GTS, and Cayenne GTS Coupe vehicles. Cracks may develop on the surface of the engine cylinder bore. Cracks may cause engine damage and a stall or an oil leak, increasing the risk of a crash or fire. Dealers will replace the engine, free of charge. Owner notification letters were mailed July 9, 2021. Owners may contact Porsche customer service at 1-800-767-7243. Porsche's number for this recall is AMB1.

21V-341

BMW of North America, LLC (BMW) is recalling certain 2021 BMW 230i and M240i vehicles. Supports within the roof liner may be insecurely attached. The support may separate from the roof liner and fall into the passenger compartment, increasing the risk of injury during a crash necessitating the deployment of the head air bag. Dealers will inspect and repair or replace the roof liner as necessary, free of charge. Owner notification letters will not be sent. The one owner was notified on June 15, 2021 by telephone and the vehicle has been repaired. Owners may contact BMW customer service at 1-800-525-7417.

21V-342

Gulf Stream Coach, Inc. (Gulf Stream) is recalling certain 2021 Vista Cruiser, Vintage Cruiser, Gulf Breeze, Matrix, Streamlite, Express, Envision, and Geo travel trailers. The Federal Certification Label may have incorrect tire size and tire pressure information listed. As such, these vehicles fail to comply with the requirements of 49 CFR Part 567, "Certification" and Federal Motor Vehicle Safety Standard number 110, "Tire Selection and Rims." The tires may be overinflated, increasing the risk of a crash. Gulf Stream will mail a replacement certification label and installation instructions, free of charge. Owner notification letters were mailed on June 28, 2021. Owners may contact Gulf Stream customer service at 1-800-2898787.

21V-343

Airstream, Inc. (Airstream) is recalling certain 2021 Interstate Nineteen vehicles. The buss bar circuit breaker may have been incorrectly wired. The wire may overheat, increasing the risk of a fire. Dealers will relabel and relocate wires, free of charge. Owner notification letters were mailed July 6, 2021. Owners may contact Airstream customer service at 1-877-596-6505 or 1-937-596-6111 ext. 7401 or 7411.

21V-344

Airstream, Inc. (Airstream) is recalling certain 2020 25RB, 26RB, 28RB, 30RB Flying Cloud, 25RB, 28RB, 30RB Flying Cloud, and 2021 25RB, 28RB, 30RB Flying Cloud, and International travel trailers. The stove top range was incorrectly installed in a non-sealed cabinet. A draft can cause the flame to enter the non-sealed cabinet, increasing the risk of a fire. Dealers will install panels/baffling in the cabinet to isolate negative airflow and prevent flame inversion, free of charge. Owner notification letters were mailed July 7, 2021. Owners may contact Airstream customer service at 1-877-596-6505 or 1-937-596-6111 ext. 7401 or 7411.

21V-345

General Motors, LLC (GM) is recalling certain 2019-2020 Chevrolet 6500HD vehicles. The engine control module (ECM) was calibrated incorrectly, allowing the vehicle to exceed the tires' maximum speed rating of 75

mph. Tire failure can occur if the vehicle speed exceeds the maximum tire speed rating, increasing the risk of a crash. Dealers will update the ECM software, free of charge. Owner notification letters were mailed June 7, 2021. Owners may contact Chevrolet customer service at 1-800-222-1020. GM's number for this recall is N202325530.

21V-346

Shyft Group is recalling certain 2021 Spartan RV Chassis K2. The rear suspension mounting bracket may be improperly welded on top of the rear drive axle. The mounting bracket may break, allowing the axle to shift and increasing the risk of a crash. Dealers will inspect and replace the rear drive axle as necessary, free of charge. Owner notification letters were mailed on May 14, 2021. Owners may contact Shyft Group customer service at 1-800-582-3454. Shyft Group's number for this recall is 21-12.

21V-347

Prevost Cars, Inc. (Prevost) is recalling 2021 X3 Commuter Coach. Parts of the seat belt installed at flip-up seats may have been incorrectly assembled, causing the shoulder strap to sit improperly on a person in a wheelchair. An improperly positioned seat belt increases the risk of an injury. Prevost will provide inspection and repair instructions, free of charge. Owner notification letters were mailed on July 11, 2021. Owners may contact Prevost customer service at 1-866-870-2046. Prevost's number for this recall is SR21-301.

21V-348

Ferrara Fire Apparatus, Inc. (Ferrara) is recalling certain 2017-2020 Inferno and Igniter vehicles. The sealing washer may not seat correctly in the pilot bore holes, allowing the high pressure fuel rail assembly to leak. A fuel leak in the presence of an ignition source increases the risk of a fire. Dealers will inspect the rail threads, and replace the rail as necessary, free of charge. Owner notification letters were mailed on June 7, 2021. Owners may contact Ferrara customer service at 1-800-443-9006.

21V-349

Forest River, Inc. (Forest River) is recalling certain 2021 Coachmen Spirit Travel Trailers. The Breakaway switch power lead is wired incorrectly and may lose power. The trailer brakes may not engage if the breakaway switch does not have power, increasing the risk of a crash. Dealers will rewire the breakaway switch, free of charge. Owner notification letters were mailed on June 9, 2021. Owners may contact Forest River customer service at 1-574-825-8205. Forest River's number for this recall is 220-1336.

21V-350

Nova Bus is recalling certain 2016-2020 LFS and LFS Artic vehicles. The sealing washer may not seat correctly in the pilot bore holes, allowing the high pressure fuel rail assembly to leak. A fuel leak in the presence of an ignition source increases the risk of a fire. Dealers will inspect the rail threads, and replace the rail as necessary, free of charge. Owner notification letters were mailed on July 9, 2021. Owners may contact Nova Bus customer service at 1-800-350-6682.

21V-351

Gillig, LLC. (Gillig) is recalling certain 2017-2020 Low Floor vehicles. The sealing washer may not seat

correctly in the pilot bore holes, allowing the high pressure fuel rail assembly to leak. A fuel leak in the presence of an ignition source increases the risk of a fire. Gillig will inspect the rail threads, and replace the rail as necessary, free of charge. Owner notification letters were mailed on August 27, 2021. Owners may contact Gillig customer service at 1-510-264-5073 or 1-800-735-1500.

21V-352

Mercedes-Benz USA, LLC (MBUSA) is recalling certain 2019-2021 G550 and G63 AMG vehicles. Components within the door latch may prevent the rear doors from latching or opening properly. The rear door may appear closed even when the latch is not fully engaged, allowing the door to open while driving and increasing the risk of injury or a crash. Damaged latch components may prevent the rear door from being opened while inside the vehicle, increasing the risk of injury. Dealers will replace the rear door latches, free of charge. Owner notification letters were mailed July 9, 2021. Owners may contact MBUSA customer service at 1-800-367-6372. Note: Vehicles repaired prior to this recall must return to dealers to have remedy performed. MBUSA's numbers for this recall are 2021060007 and 2021060014.

21V-353

Mercedes-Benz USA, LLC (MBUSA) is recalling certain 2019-2021 CLA-Class, GLE/GLS-Class, A-Class, E-Class, E-Class Coupe and Convertible, GLA/GLB-Class, GLC-Class, CLS-Class, and AMG GT-Class 4-door Coupe vehicles. Please refer to MBUSA's recall report for specific vehicle model details. The MBUX multimedia system software may cause the display to remain black, or reboot after startup. This could result in the rearview camera image not displaying properly. As such, these vehicles fail to comply with the requirements of Federal Motor Vehicle Safety Standard (FMVSS) number 111, "Rear Visibility." A backup camera that displays a blank image reduces the driver's rear view, increasing the risk of a crash or injury. The multimedia system software will be updated by a dealer, or through an over-the-air (OTA) update, free of charge. Owner notification letters were mailed beginning June 28, 2021. Owners may contact MBUSA customer service at 1-800-367-6373. MBUSA's number for this recall is 2021050012.

21V-354

VanLeigh RV (VanLeigh) is recalling certain 2019-2021 Beacon and 2019-2022 Vilano coaches. The water heater housing may not have been properly sealed, allowing gas to enter the coach. Gas inside the coach increases the risk of a fire. Dealers will install a grommet ensuring the sleeve is facing out and use zip-ties to secure the sleeves to the gas line, free of charge. The manufacturer has not yet provided a schedule for recall notification. Owners may contact VanLeigh customer service at 1-662-612-4040.

21V-355

Roadtrek Inc. (Roadtrek) is recalling certain 2020-2021 Zion, Zion SRT, and Play motorhomes. The undermount generator that charges the Absorbed Glass Mat (AGM) house batteries may have a faulty internal regulator, which could damage the AGM batteries and cause electrical system failure. Damaged AGM battery caps can detach. In addition, a damaged AGM battery that is replaced with a lead-acid battery can lead to an acid spill. Either of these scenarios can increase the risk of injury. Dealers will inspect and if necessary, replace the undermount AGM generator, free of charge. Owner notification letters were mailed May 26, 2021. Owners may contact Roadtrek customer service at 1-888-762-3873.

SAFETY DEFECT/NONCOMPLIANCE NOTICES
RECEIVED DURING MAY 2021

Published September 16, 2021

21V-356

Daimler Trucks North America, LLC (DTNA) is recalling certain 2017-2022 Freightliner Cascadia vehicles equipped with halogen headlight assemblies. The halogen headlight bulb may dislodge during replacement and contact other vehicle components, possibly causing them to melt. Melting components can increase the risk of fire. Dealers will install a foam grommet, cut a 4-inch access hole into the inner fender, and add a warning label on both fenders, free of charge. Owner notification letters were mailed on July 9, 2021. Owners may contact DTNA customer service at 1-800-547-0712. DTNA's number for this recall is FL-887.

21V-357

Sutphen Corporation (Sutphen) is recalling one 2012 SP70 vehicle equipped with a Weldon V-Mux Vista IV Standard LCD display used for controlling emergency vehicle lighting and HVAC functions. The display may experience low voltage spikes, causing the LCD display to lock up or become non-functional, due to varying electrical installations. A locked up or non-functional LCD display can delay emergency efforts, which can increase the risk of injury. A dealer has repaired the affected vehicle, and therefore no owner notification letters will be sent. Owners may contact Sutphen customer service at 1-614-889-1005.

21V-358

Daimler Vans USA, LLC (DVUSA) is recalling certain 2020 Mercedes-Benz Sprinter vehicles. The screws for the front door hinges may not have been tightened properly. Loose door hinge screws could change the gap between the door and vehicle body, increasing the risk of injury in the event of a crash. Dealers will check the screws and tighten them as necessary, free of charge. Owner notification letters were mailed June 18, 2021. Owners may contact DVUSA customer service at 1-877-762-8267. DVUSA's number for this recall is VS3TURSCHA.

21V-359

Daimler Vans USA, LLC (DVUSA) is recalling certain 2019 Mercedes-Benz Sprinter vehicles equipped with the camper upfit option. The Electronic Stability Control (ESP) software was not updated for vehicles with a higher center of gravity. The ESP may not respond as intended during certain driving scenarios, increasing the risk of a crash. Dealers will update the software, free of charge. Owner notification letters were mailed on July 2, 2021. Owners may contact DVUSA customer service at 1-877-762-8267. DVUSA's number for this recall is VS3HOLAPLI.

21V-360

Ducati North America (Ducati) is recalling certain 2021 Scrambler 800 Night Shift motorcycles. The front and rear turn signal lights may not flash brightly enough. As such, these motorcycles fail to comply with the requirements of Federal Motor Vehicle Safety Standard (FMVSS) number 108, "Lamps, Reflective Devices, and Associated Equipment." Turn signal lights that aren't bright enough can reduce other driver's ability to see that the turn signals have been activated, increasing the risk of a crash. Dealers will replace the front and rear turn signals, free of charge. Owner notification letters were mailed on June 28, 2021. Owners may contact Ducati customer service at 1-888-391-5446. Ducati's number for this recall is SRV-RCL-21-009.

21V-361

Porsche Cars North America, Inc. (Porsche) is recalling certain 2021 Taycan, Panamera, Panamera Turbo S, Panamera GTS, Panamera 4, Panamera 4 Sport Turismo, Panamera 4 Executive, Panamera 4S Executive, Panamera 4S, Panamera 4S E-Hybrid, and Panamera 4 E-Hybrid vehicles. The front lower trailing arms were not forged correctly and may break. A broken front lower trailing arm may cause a loss of vehicle control, increasing the risk of a crash. Dealers will replace the front lower trailing arms, free of charge. Interim owner notification letters informing owners of the safety risk were mailed July 16, 2021. A second notice will be mailed when the remedy becomes available. Owners may contact Porsche customer service at 1-800-767-7243. Porsche's number for this recall is AMB2.

21V-362

KTM North America, Inc. (KTM) is recalling all 2020 Husqvarna 701 Enduro LR motorcycles. The fuel lines on the front fuel tank may chafe against the tank, possibly resulting in a fuel leak. A fuel leak in the presence of an ignition source can increase the risk of a fire. Dealers will install two new fuel lines and an additional clamp, free of charge. Owner notification letters were mailed June 11, 2021. Owners may contact KTM customer service at 1-888-985-6090. KTM's number for this recall is HTB2105.

21V-363

Motor Coach Industries (MCI) is recalling certain 2017-2018 D4000, 2017-2019 D4005, D4000ISTV, D4505, 2017-2020 D4500, J4500, 2018-2020 D45CRTLE, and 2018-2021 J3500 vehicles. The sealing washer may not seat correctly in the pilot bore holes, allowing the high pressure fuel rail assembly to leak. A fuel leak in the presence of an ignition source increases the risk of a fire. Dealers will inspect the rail threads, and replace the rail as necessary, free of charge. Owner notification letters were mailed on June 28, 2021. Owners may contact MCI customer service at 1-800-241-2947. MCI's number for this recall is R21-009.

21V-364

New Flyer of America, Inc. (New Flyer) is recalling certain 2017-2021 XD40, XD35, 2016-2021 XD60, 2017 XDE35, 2016-2020 XDE40, XDE60 vehicles. The sealing washer may not seat correctly in the pilot bore holes, allowing the high pressure fuel rail assembly to leak. A fuel leak in the presence of an ignition source increases the risk of a fire. New Flyer will inspect the rail threads, and replace the rail as necessary, free of charge. Owner notification letters were mailed on June 28, 2021. Owners may contact New Flyer customer service at 1-204-224-6706. New Flyer's number for this recall is R21-008.

21V-365

Navistar, Inc. (Navistar) is recalling certain 2018-2019 International WorkStar, International DuraStar, 2019-2021 International HV, International MV, and IC Bus RE Commercial Bus vehicles. The sealing washer may not seat correctly in the pilot bore holes, allowing the high pressure fuel rail assembly to leak. A fuel leak in the presence of an ignition source increases the risk of a fire. Dealers will inspect the rail threads, and replace the rail as necessary, free of charge. Owner notification letters were mailed on June 21, 2021. Owners may contact Navistar customer service at 1-800-448-7825.

21V-366

Navistar, Inc. (Navistar) is recalling certain 2019-2021 IC Bus RE School Buses. The sealing washer may not

seat correctly in the pilot bore holes, allowing the high pressure fuel rail assembly to leak. A fuel leak in the presence of an ignition source increases the risk of a fire. Dealers will inspect the rail threads, and replace the rail as necessary, free of charge. Owner notification letters were mailed on June 21, 2021. Owners may contact Navistar customer service at 1-800-448-7825.

21V-367

Keystone RV Company (Keystone) is recalling certain 2021 High Country Montana trailers. The 120VAC wiring connectors for the slide room circuit were not mounted properly, which can allow water to enter the electrical connections. Wet electrical connections can increase the risk of a fire. Dealers will inspect the connectors, and mount the connectors to the frame, free of charge. Owner notification letters were mailed on June 18, 2021. Owners may contact Keystone customer service at 1-866-425-4369. Keystone's number for this recall is 21-409.

21V-368

Daimler Trucks North America, LLC (DTNA) is recalling certain 2021-2022 Freightliner 114SD, 122SD, Business Class M2, Cascadia, 108SD, Western Star 4900, 4700, 5700, Custom Chass RV Chassis, Custom Chass S2 Chassis, Custom Chass XC Chassis, Custom Chass XB Chassis, and Custom Chass MT Chassis. The tie rod clamps may be loose, which could result in loose tie rod ends that could break or detach. Detached or broken tie rod ends can result in steering loss, increasing the risk of a crash. Dealers will replace the tie rod clamp bolts and nuts, free of charge. Interim owner notification letters were mailed on July 16, 2021. Owners may contact DTNA customer service at 1-800-547-0712. DTNA's number for this recall is FL-888.

21V-369

Daimler Trucks North America, LLC (DTNA) is recalling certain 2021-2022 Thomas Built Saf-T-Liner HDX School Buses and Saf-T-Liner C2 School Buses. The tie rod clamps may be loose, which could result in loose tie rod ends that could break or detach. Detached or broken tie rod ends can result in steering loss, increasing the risk of a crash. Dealers will replace the tie rod clamp bolts and nuts, free of charge. Interim owner notification letters were mailed on July 16, 2021. Owners may contact DTNA customer service at 1-800-547-0712. DTNA's number for this recall is FL-888.

21V-370

Forest River, Inc. (Forest River) is recalling certain 2021 Columbus Fifth Wheel trailers. The legs on the Allure Swivel Dining chair may detach from the chair body. There would be an increased risk of injury if the chair legs detach while the chair is occupied. Dealers will install a hardware kit to reinforce the chair legs, free of charge. Owner notification letters were mailed June 9, 2021. Owners may contact Forest River customer service at 1-574-821-1487. Forest River's number for this recall is 410-1342.

21V-371

Newmar Corporation (Newmar) is recalling certain 2017-2022 Dutch Star, 2017-2019 Mountain Aire, 2019-2021 Ventana and 2021 New Aire motorhomes. The sealing washer may not seat correctly in the pilot bore holes, allowing the high pressure fuel rail assembly to leak. A fuel leak in the presence of an ignition source increases the risk of a fire. Dealers will inspect the rail threads, and replace the rail as necessary, free of charge.

Interim notification letters were mailed to owners July 16, 2021. Owners may contact Newmar customer service at 1-800-731-8000. Newmar's number for this recall is Cummins 21E-032.

21V-372

Nissan North America, Inc. (Nissan) is recalling certain 2020-2021 Nissan Armada and 2020-2021 INFINITI QX80 vehicles equipped with V8 engines. The impeller can swell and bind within the fuel pump module, causing it to fail. Fuel pump failure can cause an engine stall, increasing the risk of a crash. Dealers will replace the fuel pump module, free of charge. Nissan issued owners an interim notification on July 19, 2021. Owners may contact Nissan customer service at 1-800-867-7669. Nissan's number for this recall is R21A2. Owners may contact INFINITI customer service at 1-800-662-6200. INFINITI's number for this recall is R21A3.

21V-373

Forest River, Inc. (Forest River) is recalling certain 2021 Columbus Fifth Wheel trailers. The breakaway switch and trailer brakes may not activate when needed due to an incorrectly wired breakaway switch. Failure of the breakaway switch and trailer brakes can increase the risk of a crash or injury. Dealers will rewire the breakaway switch, free of charge. Owner notification letters were mailed June 9, 2021. Owners may contact Forest River customer service at 1-574-821-1487. Forest River's number for this recall is 410-1350.

21V-374

Tiny Idahomes LLC (Tiny Idahomes) is recalling certain 2019 RMCRV K2 trailers equipped with Dometic 3-burner cooking stoves. The saddle valve securing bolt may be overtightened, possibly damaging the o-ring seal and causing a continuous gas leak. A gas leak can increase the risk of a fire. Tiny Idahomes will notify owners, and Dometic service centers will install a remedy kit of gaskets, washers, thread locker bolts, and two round orange labels, free of charge. Owner notification letters were mailed on June 14, 2021. Owners may contact Tiny Idahomes customer service at 1-208-468-0576.

21V-375

Ford Motor Company (Ford) is recalling certain 2013-2021 Transit Connect vehicles equipped with 2.5L engines. The bushing that attaches the shifter cable to the transmission may degrade or detach. A damaged or missing bushing may prevent the vehicle from shifting into the intended gear, causing the vehicle to move in an unexpected direction. Additionally, the vehicle may roll after the driver selects the 'Park' position. Either scenario increases the risk of a crash or injury. Dealers will replace the underhood shifter cable bushing, and add a protective cap, free of charge. Owner notification letters were mailed on June 29, 2021. Owners may contact Ford customer service at 1-866-436-7332. Ford's number for this recall is 21S24.

21V-376

Ford Motor Company (Ford) is recalling certain 2021 Edge vehicles. The driver's seat belt retractor pretensioner assembly may not function correctly when activated during a crash. As such, these vehicles fail to comply with the requirements of Federal Motor Vehicle Safety Standard (FMVSS) number 208, "Occupant Crash Protection." A seatbelt assembly that does not function as intended can increase the risk of injury during a crash. Dealers will replace the driver's seat belt retractor pretensioner assembly, free of charge. Owner notification letters were mailed on June 15, 2021. Owners may contact Ford customer service at 1-866-436-

7332. Ford's number for this recall is 21C13.

21V-377

Forest River, Inc. (Forest River) is recalling certain 2021 Sierra and Sandpiper Fifth Wheel and Travel Trailers. The bolts that hold the floor to the chassis were improperly tightened. Improperly tightened bolts could cause the trailer body to detach from the chassis, increasing the risk of a crash. Dealers will tighten the bolts to the chassis outriggers, free of charge. Owner notification letters were mailed June 9, 2021. Owners may contact Forest River customer service at 1-574-534-4574. Forest River's number for this recall is 03-1347.

21V-378

Ford Motor Company (Ford) is recalling certain 2021 Super Duty F-350 and F-450 vehicles equipped with a fifth wheel left-hand mounting bracket that may be cracked. A cracked mounting bracket could result in the fifth wheel detaching from the vehicle while towing, increasing the risk of a crash. Dealers will inspect the mounting bracket, and replace the bracket if necessary, free of charge. Owner notification letters were mailed on June 16, 2021. Owners may contact Ford customer service at 1-866-436-7332. Ford's number for this recall is 21S23.

21V-379

Keystone RV Company (Keystone) is recalling certain 2017-2021 Keystone Cougar 368MBI trailers. The frame rails do not have enough cross support, which could cause them to buckle under certain side-load stress conditions. A buckled frame rail can increase the risk of a crash. Dealers will add cross braces between each spring hanger and an outrigger between the tires on the off-door side of the vehicle, free of charge. Owner notification letters were mailed July 15, 2021. Owners may contact Keystone customer service at 1-866-425-4369. Keystone's number for this recall is 21-411.

21V-380

Ford Motor Company (Ford) is recalling certain 2021 F-150 vehicles. The two-piece driveshafts may have been improperly assembled, which could result in driveshaft separation. Driveshaft separation may result in a sudden loss of drive power, or unintended vehicle movement if the vehicle is in park without the parking brake applied, increasing the risk of a crash. Dealers will inspect the driveshaft, and replace it if necessary, free of charge. Owner notification letters were mailed on June 15, 2021. Owners may contact Ford customer service at 1-866-436-7332. Ford's number for this recall is 21S25.

21V-381

Honda (American Honda Motor Co.) is recalling certain 2020-2021 Super Cub C125, CB500X, CB650R, CBR300R, CBR500R, CBR650R, Rebel 300, Rebel 500, Monkey, 2020 CRF250L, GROM, 2021 CRF300L, and CB500F motorcycles. The rear reflector lens may not reflect brightly enough. As such, these vehicles fail to comply with the requirements of Federal Motor Vehicle Safety Standard (FMVSS) number 108, "Lamps, Reflective Devices, and Associated Equipment." A dim rear reflector may reduce the visibility of the motorcycle to other drivers, increasing the risk of a crash or injury. Dealers will replace the rear reflector, free of charge. Owner notification letters were mailed July 7, 2021. Owners may contact Honda customer service at 1-866-784-1870. Honda's number for this recall is KM3.

21V-382

Great Dane Trailers (Great Dane) is recalling certain 2022 Champion trailers equipped with air disc brakes. The brake caliper mounting bolts may be insufficiently tightened, allowing the bolts to loosen. Loose brake caliper mounting bolts can reduce brake effectiveness, increasing the risk of a crash. Dealers will inspect and tighten the caliper mounting bolts, free of charge. Owner notification letters were mailed on June 28, 2021. Owners may contact Great Dane customer service at 1-877-369-3493.

21V-383

Life Line Emergency Vehicles (Life Line) is recalling certain 2019-2020 Dodge 5500 vehicles. The rear brake caliper flexible line may have been improperly routed, which could allow it to chafe against suspension components, and result in a brake fluid leak. A brake fluid leak can cause a loss of brakes and increase the risk of a crash. Dealers will modify the rear brake caliper flexible line mounting, and replace the rear brake caliper flexible line as needed, free of charge. Owner notification was mailed on May 13, 2020. Owners may contact Life Line customer service at 1-563-578-3317 ext. 132.

21V-384

Van Hool N.V. (Van Hool) is recalling certain 2018-2021 CX35, TDX25, 2018-2019 CX45, TX45, 2021 AG300, and 2018 TD925 vehicles. The sealing washer may not seat correctly in the pilot bore holes, allowing the high pressure fuel rail assembly to leak. A fuel leak in the presence of an ignition source increases the risk of a fire. Dealers will inspect the rail threads, and replace the rail as necessary, free of charge. Owner notification letters were mailed on June 18, 2021. Owners may contact Van Hool customer service at 1-877-427-7278 or 1-407-656-7977. Van Hool's number for this recall is P1489.

21V-385

Seagrave Fire Apparatus, LLC (Seagrave) is recalling certain 2017-2020 Marauder, Attacker and Capitol vehicles. The sealing washer may not seat correctly in the pilot bore holes, allowing the high pressure fuel rail assembly to leak. A fuel leak in the presence of an ignition source increases the risk of a fire. Dealers will inspect the rail threads, and replace the rail as necessary, free of charge. Owner notification letters were mailed on June 18, 2021. Owners may contact Seagrave customer service at 1-877-777-5360.

21V-386

Tesla, Inc. (Tesla) is recalling certain 2019-2021 Model 3 and 2020-2021 Model Y vehicles. The brake caliper bolts may be loose, allowing the brake caliper to separate and contact the wheel rim. Contact with the rim may cause a loss of tire pressure, increasing the risk of a crash. Tesla Service will inspect and tighten, or replace the caliper bolts as necessary, free of charge. Owner notification letters were mailed July 23, 2021. Owners may contact Tesla customer service online by visiting www.tesla.com/support/contact or by calling 1-877-79-TESLA (or 1-877-798-3752). Tesla's number for this recall is SB-21-33-002.

21V-387

Tesla, Inc. (Tesla) is recalling certain 2019-2021 Model Y vehicles. One or both fasteners that secure the left and right second row seat belt retractors may not be properly attached. Improperly attached fasteners may prevent the seat belt retention system from performing as designed, increasing the risk of injury. Tesla Service will inspect and replace both fasteners if necessary, free of charge. Owner notification letters were mailed July

23, 2021. Owners may contact Tesla customer service online by visiting www.tesla.com/support/contact or by calling 1-877-79-TESLA (or 1-877-798-3752). Tesla's number for this recall is SB-21-20-002.

21V-388

Tesla, Inc. (Tesla) is recalling certain 2018-2020 Model 3 and 2019-2021 Model Y vehicles. One or both fasteners that secure the front seat shoulder belt to the b-pillar may not be properly attached. An improperly attached fastener may prevent the seat belt system from performing as designed, increasing the risk of injury. Tesla Service will inspect and repair both fasteners if necessary, free of charge. Owner notification letters were mailed July 23, 2021. Owners may contact Tesla customer service online by visiting www.tesla.com/support/contact or by calling 1-877-79-TESLA (or 1-877-798-3752). Tesla's number for this recall is SB-21-20-001.

21V-389

Ford Motor Company (Ford) is recalling certain 2021 F-350, F-450, F-550, and F-600 vehicles equipped with dual rear wheels and front wheel hub extenders. The front wheel hub extenders may be improperly attached to the front rotor hub assemblies, which could result in separation of the wheels and wheel extenders from the vehicle. A detached wheel and wheel extender can increase the risk of a crash. Dealers will inspect and tighten the front wheel hub extender nuts, free of charge. Owners are instructed not to drive their vehicles until the torque of the wheel extender nuts can be verified. Owner notification letters were mailed on June 18, 2021. Owners may contact Ford customer service at 1-866-436-7332. Ford's number for this recall is 21S26.

21V-390

PACCAR Incorporated (PACCAR) is recalling certain 2018-2021 Peterbilt 337, 348, 365, 367, 520, 567, Kenworth T270, T370, T440, T470, T800 and T880 vehicles. The sealing washer may not seat correctly in the pilot bore holes, allowing the high pressure fuel rail assembly to leak. A fuel leak in the presence of an ignition source increases the risk of a fire. Dealers will inspect the rail threads and fuel lines, and replace the rail as necessary, free of charge. Owners may contact PACCAR customer service at 1-425-828-5888 (Kenworth) or 1-940-591-4220 (Peterbilt). PACCAR's numbers for this recall are 21KWC and 21PBD.

21V-391

Daimler Trucks North America, LLC (DTNA) is recalling certain 2019 Freightliner eBusiness Class M2 vehicles equipped with 14Xe ePowertrains. The stator assembly wires may have been insufficiently crimped, causing high resistance, overheating, and preventing the high voltage system from starting. A loss of power to the system may cause a loss of drive power, increasing the risk of a crash. Dealers will replace the motor stator, free of charge. All units were remedied by July 13, 2021. Owners may contact DTNA customer service at 1-800-547-0712. DTNA's number for this recall is FL-889.

21V-392

Grand Design RV, LLC (Grand Design) is recalling certain 2016-2021 Imagine, Transcend, and Momentum travel trailers. The LP regulator that controls the LP gas pressure may fail, allowing excessive gas pressure that causes the appliance flame to increase. Excessive gas pressure and a larger than intended appliance flame can increase the risk of a fire. Dealers will replace the LP regulator, free of charge. Owner notification letters were

mailed June 24, 2021. Owners may contact Grand Design customer service at 1-574-825-9679. Grand Design's number for this recall is 910023.

21V-393

Pierce Manufacturing (Pierce) is recalling certain 2017-2021 Arrow XT, Enforcer, Impel, Quantum, Saber, and Velocity vehicles. The sealing washer may not seat correctly in the pilot bore holes, allowing the high pressure fuel rail assembly to leak. A fuel leak in the presence of an ignition source increases the risk of a fire. Dealers will inspect the rail threads and fuel lines, and replace the rail as necessary, free of charge. Interim notification letters were mailed to owners on June 24, 2021. Owners may contact Pierce customer service at 1-888-974-3723.

21V-394

REV Recreation Group (REV) is recalling certain 2017-2021 Fleetwood Bounder P Model, Holiday Rambler Vacationer P Model, and 2018-2021 Fleetwood Southwind Model P motorhomes. The floor may have improperly sealed holes that could allow gases such as carbon monoxide to enter the living area. Gases entering the living area increases the risk of an injury and/or death. Dealers will reseal the floor area, free of charge. Interim owner notification letters were mailed on July 22, 2021. Owners may contact REV customer service at 1-800-509-3417. REV's number for this recall is 210521REV.

21V-395

Thor Motor Coach (TMC) is recalling certain 2022 Rize, Scope, Sequence, and Tellaro vehicles. The Flex-190 Solar Panel junction box may short. An electrical short can cause the junction box to overheat, increasing the risk of a fire. Dealers will install a new solar panel and junction box, free of charge. Owner notification letters were mailed July 22, 2021. Owners may contact TMC customer service at 1-877-855-2867. TMC's number for this recall is RC000226.

21V-396

KZRV, L.P. (KZRV) is recalling certain 2021 Stratus and SportTrek trailers. The water heater circuits were wired with an incorrect size circuit breaker, which may prevent the breaker from tripping, and failing to provide adequate wiring protection. Inadequate wiring protection can increase the risk of a fire. Dealers will replace the 20 amp circuit breaker with a 15 amp circuit breaker, free of charge. Owner notification letters were mailed July 13, 2021. Owners may contact KZRV customer service at 1-800-768-4016 ext. 154 or 153. KZRV's number for this recall is KZ-2021-02.

21V-397

Chrysler (FCA US, LLC) is recalling certain 2012-2021 RAM 3500, 3500 Cab Chassis, 4500 Cab Chassis, and 5500 Cab Chassis vehicles. Incorrect information in the Service and Owner's Manuals may cause the flanged lug nuts to be over-tightened, which could result in a broken wheel stud and possible wheel separation. Wheel separation can cause a vehicle crash. Dealers will update the torque specification in the owner's manual and other published service documents. Dealers will also inspect the vehicle's wheel studs, replacing them if necessary, free of charge. Owner notification letters were mailed on August 17, 2021. Campaign Y26 owner notification letters are expected to be mailed on December 28, 2021. Owners may contact FCA US customer

service at 1-800-853-1403. FCA US's numbers for this recall are Y26 and Y36.

21V-398

Temsa is recalling certain 2018-2021 TS35 and 2018-2020 TS45 vehicles. The sealing washer may not seat correctly in the pilot bore holes, allowing the high pressure fuel rail assembly to leak. A fuel leak in the presence of an ignition source increases the risk of a fire. Cummins will inspect the rail threads and fuel lines, and replace the rail as necessary, free of charge. Owner notification letters were mailed on July 30, 2021. Owners may contact Temsa customer service at 1-800-625-9319.

21V-399

Triple E Recreational Vehicles (Triple E) is recalling certain 2020-2021 Serenity S24CB, Unity U24MB, U24CB, U24IB, U24FX, U24TB, U24RL, Wonder W24RL, W24MB, W24FTB, and W24RTB recreational vehicles. The metal deflector that protects the refrigerator's wood frame from exhaust is positioned too low, which could allow the exhaust to discolor or char the wood frame. Discoloration or charring of the wood frame can increase the risk of a fire. Dealers will install a metal deflector extension, free of charge. Owner notification letters were mailed June 30, 2021. Owners may contact Triple E customer service at 1-877-992-9906. Triple E's number for this recall is CA#9932-1.

21V-400

BMW of North America, LLC (BMW) is recalling certain 2000-2001 BMW 3 Series (323Ci, 325Ci, 328Ci and 330Ci), 1999-2001 323i, 328i, 330i, 330xi, and 2000 323i, 328i stationwagon vehicles equipped with Non-Azide Driver air bag Inflators (NADI) manufactured by Takata. These vehicles are equipped with driver-side air bag inflators that were previously inspected, but not replaced under recall numbers 19V-851, 19V852, or 19V-853. Due to a manufacturing issue, the NADI inflator may absorb moisture, causing the inflator to explode or the air bag cushion to underinflate. The inflator could explode during air bag deployment, resulting in metal fragments striking the driver or other occupants. An underinflated air bag may not properly protect the occupant. These scenarios increase the risk of serious injury or death. Dealers will replace the driver-side air bag inflator with a newly designed inflator, free of charge. Owner notification letters were mailed on July 12, 2021. Owners may contact BMW customer service at 1-800-525-7417.

21V-401

Nissan North America, Inc. (Nissan) is recalling certain 2020 Nissan Murano, INFINITI QX60, 2021 Nissan GT-R, INFINITI QX50, and Q50 vehicles. The front steering knuckle or rear axle housing may have insufficient strength due to improper heat-treatment. The steering knuckle or rear axle could deform upon impact, such as from hitting a curb, resulting in a loss of steering control, or possible wheel separation. Both of these conditions can increase the risk of a crash. Dealers will inspect and replace the front steering knuckle and rear axle housing, as necessary, free of charge. Owner notification letters were mailed July 26, 2021. Nissan owners may contact customer service at 1-800-867-7669. INFINITI owners may contact customer service at 1-800-662-6200.

21V-402

Mercedes-Benz USA, LLC (MBUSA) is recalling certain 2020 GLB250 vehicles. Water may enter through the

wheel well area into the front occupant foot wells, potentially damaging certain electrical components. This may result in the instrument cluster going blank, an engine stall while driving, or the vehicle may not start. Either a blank instrument cluster display or an engine stall can increase the risk of a crash. Dealers will seal the vehicle body in the wheel well area and inspect the front foot wells for water intrusion, repairing as necessary, free of charge. Owner notification letters were mailed July 20, 2021. Owners may contact MBUSA customer service at 1-800-367-6372. MBUSA's number for this recall is 2020070009.

21V-403

Mercedes-Benz USA, LLC (MBUSA) is recalling certain 2020 GLB250 vehicles. The side curtain air bags may not deploy properly during a crash. Air bags that do not deploy as intended can increase the risk of injury. Dealers will replace the side curtain air bags, free of charge. Owner were notified of the safety risk with an interim letter mailed July 16, 2021. A second owner letter will be mailed once the remedy is available. Owners may contact MBUSA customer service at 1-800-367-6372.

21V-404

Mercedes-Benz USA, LLC (MBUSA) is recalling certain 2020 GLB250 vehicles. The front passenger air bag inflator and cushion may be improperly attached inside the air bag module, which could result in the air bag cushion tearing upon deployment. An air bag that does not deploy properly during a crash can increase the risk of injury. Dealers will replace the front passenger air bag module, free of charge. Owner notification letters were mailed July 16, 2021. Owners may contact MBUSA customer service at 1-800-367-6372. MBUSA's number for this recall is 2021060011.

21V-405

Mercedes-Benz USA, LLC (MBUSA) is recalling certain 2021 C300 Cabriolet, C43 AMG Cabriolet, C63 AMG Cabriolet, C63 AMG S Cabriolet, E450 Cabriolet, and E53 AMG Cabriolet vehicles. The rear headrests may be incorrectly mounted to the seatbacks. Incorrectly mounted headrests could move or detach from the seat during a crash, increasing the risk of injury. Dealers will inspect the rear seatback guide bushings and replace them if necessary, free of charge. Owner notification letters were mailed July 16, 2021. Owners may contact MBUSA customer service at 1-800-367-6372. MBUSA's number for this recall is 2021060010.

21V-406

Ford Motor Company (Ford) is recalling certain 2021 F-150 vehicles. The steering gear may have internal damage, which could result in difficulty steering, or the inability to rotate the steering wheel while driving. Loss of steering control can increase the risk of a crash. Owners are advised to not drive their vehicles until the repair is complete. Vehicles will be towed in for service, and dealers will remove and replace the steering gear, free of charge. Owner notification letters were mailed on June 4, 2021. Owners may contact Ford customer service at 1-866-436-7332. Ford's number for this recall is 21S28.

21V-407