

**Products Liability Law Daily Wrap Up, NHTSA NEWS—MOTOR VEHICLES
—Land Rover recalls over 58K vehicles due to rearview camera
issues, (Jan. 24, 2024)**

Products Liability Law Daily Wrap Up

[Click to open document in a browser](#)

By Joe Cox, J.D.

Dealers will inspect the rearview camera and add a new seal or replace the camera.

Jaguar Land Rover North America, LLC (Land Rover) is recalling approximately 58,729 2018-2022 Range Rover and Range Rover Sport vehicles equipped with a Surround Camera System because water may enter into the rearview camera, which can cause the rearview camera image not to appear on the display or display a distorted image. As such, these vehicles fail to comply with the requirements of Federal Motor Vehicle Safety Standard (FMVSS) No. 111, *Rear Visibility*. A rearview camera image that does not display while the vehicle is in reverse decreases the driver's visibility, increasing the risk of injury or a crash (*NHTSA Recall Notice*, No. 24V023, Report receipt date: January 18, 2024).

Remedy. Dealers will inspect the rearview camera and add a new seal or replace the camera, free of charge. Owner notification letters are expected to be mailed March 8, 2024.

Contact information. Owners may contact Land Rover customer service at 1-800-637-6837. Land Rover's number for this recall is N778. Owners may also contact the National Highway Traffic Safety Administration Vehicle Safety Hotline at 1-888-327-4236 (TTY 1-800-424-9153) or go to www.nhtsa.gov.

Companies: Jaguar Land Rover North America, LLC

ProductRecalls: ProductRecallsNews MotorVehiclesNews RecallNewsStory